

**WPD - Creeks Inspected**  
**Between 1/1/2007 And 12/31/2008**

Site ID	Address	Map Page	Watershed	Insp. Date	Inspection Commen
77	12100 Metric Blvd	466X	WLN	2/15/2007	ok
77	12100 Metric Blvd	466X	WLN	8/2/2007	ok
77	12100 Metric Blvd	466X	WLN	6/20/2008	
78	12100 N Lamar Blvd	496G	WLN	2/15/2007	ok
78	12100 N Lamar Blvd	496G	WLN	8/9/2007	ok
78	12100 N Lamar Blvd	496G	WLN	6/20/2008	
79	12100 W I 35 Hwy	496M	WLN	2/15/2007	ok
79	12100 W I 35 Hwy	496M	WLN	8/9/2007	ok
79	12100 W I 35 Hwy	496M	WLN	6/20/2008	
81	11400 Dessau Rd	497S	WLN	2/15/2007	ok
81	11400 Dessau Rd	497S	WLN	8/9/2007	ok
81	11400 Dessau Rd	497S	WLN	6/20/2008	
87	12506 Parmer La	466U	WLN	3/8/2007	Construction on upstream - ok
87	12506 Parmer La	466U	WLN	8/2/2007	ok
87	12506 Parmer La	466U	WLN	6/20/2008	
480	Old Cedar	466Y	WLN	3/8/2007	ok
480	Old Cedar	466Y	WLN	8/2/2007	ok
480	Old Cedar	466Y	WLN	6/27/2008	
482	1600 Cedar Bend	466X	WLN	3/8/2007	ok
482	1600 Cedar Bend	466X	WLN	6/20/2007	
482	1600 Cedar Bend	466X	WLN	8/2/2007	ok

**WPD - Creeks Inspected**  
**Between 1/1/2007 And 12/31/2008**

Site ID	Address	Map Page	Watershed	Insp. Date	Inspection Commen
483	12300 Running Bird	466X	WLN	3/8/2007	Upstream - concrete mix sacks in creek. Large dead trees down across creek. A lot of trash in creek. Culvert blocked upstream due to heavy brush. Downstream - Erosion between top of culvert and pavement. Ok.
					ACTION: Remove tree/brush/debris for 100-ft upstream of crossing. SRP requires removal by hand and no equipment in the creek. Tree removal is limited to the fallen willow tree upstream.
483	12300 Running Bird	466X	WLN	8/2/2007	Work order submitted last round of inspections is still open.
483	12300 Running Bird	466X	WLN	6/20/2008	
484	12400 Metric	466T	WLN	2/15/2007	Ok.
484	12400 Metric	466T	WLN	8/2/2007	ok
484	12400 Metric	466T	WLN	6/20/2008	
516	Willow Wild	496C	WLN	3/8/2007	ok
516	Willow Wild	496C	WLN	8/2/2007	ok
516	Willow Wild	496C	WLN	6/20/2008	
716	11610 February Dr	497N	WLN	8/7/2008	ok

**Number of Inspections      31**